

|                                                  | ACEA           | API                                      | ILSAC                    | Volkswagen                 | Mercedes                                     | BMW                                             | Opel                                                           | GM                                                    | Ford                                                         | Renault               | PSA                  | Stellantis    | Fiat                                                     | Volvo                    | Porsche | Chrysler             | Jaguar /<br>Land Rover         | Iveco          | Bentley                      |
|--------------------------------------------------|----------------|------------------------------------------|--------------------------|----------------------------|----------------------------------------------|-------------------------------------------------|----------------------------------------------------------------|-------------------------------------------------------|--------------------------------------------------------------|-----------------------|----------------------|---------------|----------------------------------------------------------|--------------------------|---------|----------------------|--------------------------------|----------------|------------------------------|
| <b>AVIA</b> Dynetic <i><b> racing</b></i> 10W-60 | A3/B4          | SN/CF                                    |                          | 501 01<br>505 00           | MB 229.3                                     | Longlife-01                                     |                                                                |                                                       |                                                              |                       |                      |               |                                                          |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-LL Premium 5W-30             | C2<br>C3       | SQ<br>SP/SN PLUS                         |                          | 504 00<br>507 00<br>503 01 | MB 229.31; MB 229.51<br>MB 229.52            | Longlife-04                                     | OV 0401547-D30<br>OV 0401547-G30<br>GM-LL-A-025<br>GM-LL-B-025 | GM dexos 1™ Gen 2<br>GM dexos 2™                      |                                                              |                       |                      |               | 9.55535-S3                                               |                          | C30     |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-LL VS 0W-30                  | C2<br>C3       | SN                                       |                          | 504 00<br>507 00           | MB 229.31; MB 229.51<br>MB 229.52            | Longlife-04<br>Longlife-19 FE                   |                                                                |                                                       |                                                              |                       |                      |               | 9.55535-GS1<br>9.55535-DS1<br>9.55535-S3                 |                          | C30     |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-LL FE 0W-20                  | C5<br>C6       | SP; SP/RC<br>SN PLUS                     | GF-6 A                   | 508 00;<br>509 00          |                                              |                                                 |                                                                |                                                       | M2C956-A1                                                    |                       |                      |               |                                                          |                          | C20     |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-BM Extrem 0W-30              | C2<br>C3       | SP                                       |                          |                            | MB 226.5; MB 229.31<br>MB 229.51             | Longlife-04<br>Longlife-12 FE<br>Longlife-19 FE | OV 0401547-D30-G30                                             |                                                       |                                                              | RN0700/RN0710         |                      |               | 9.55535-DS1<br>9.55535-GS1                               |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-BM Premium 0W-30             | A5/B5<br>C2    | SP/RC<br>SP/SN PLUS                      | GF-5<br>GF-6 A           | 530 35                     | MB 229.61<br>DTFR 15D100                     | Longlife-12 FE                                  | OV 0401547-G30                                                 |                                                       | M2C950-A<br>M2C957-A1                                        |                       |                      |               | 9.55535-DS1<br>9.55535-GS1                               |                          |         |                      | STJLR.03.5007                  |                |                              |
| <b>AVIA</b> Dynetic-BM FE 0W-20                  | C5/C6          | SP/RC<br>SQ                              | GF-6 A<br>GF-7 A         |                            | MB 229.71; MB 229.72                         | Longlife-17 FE+                                 | OV 040 1547-A20                                                |                                                       | M2C947-B1<br>M2C954-A1<br>M2C962-A1                          |                       |                      |               | 9.55535-GSX                                              | VCC C6SP                 |         | MS 12145             | STJLR.03.5006                  |                |                              |
| <b>AVIA</b> Dynetic-BM Superior 0W-20            | C5<br>C6       | SQ; SQ/RC<br>SP; SP/RC<br>SN PLUS; SN/RC | GF-5<br>GF-6 A<br>GF-7 A | 530 57                     | MB 229.71; MB 229.72                         | Longlife-14 FE+<br>Longlife-17 FE+              | OV 0401547-A20                                                 | GM dexos 1™ Gen 3<br>GM dexos D™                      | M2C947-A<br>M2C947-B1<br>M2C952-A1<br>M2C954-A1<br>M2C962-A1 |                       |                      |               | 9.55535-CR1<br>9.55535-DM1<br>9.55535-DSX<br>9.55535-GSX | VCC C6SP<br>VCC RBS0-2AE |         | MS-12145<br>MS-6395  | STJLR.03.5006<br>STJLR.51.5122 |                |                              |
| <b>AVIA</b> Dynetic-SP Premium 5W-30             | C2<br>C3       | SN; SP; SQ<br>SN PLUS                    |                          | 505 00<br>505 01<br>502 00 | MB 226.52; MB 229.31<br>MB 229.51; MB 229.52 | Longlife-04                                     | OV 0401547-D30<br>OV 0401547-G30<br>GM-LL-A-025/B-025          | GM dexos 1™ Gen 2<br>GM dexos 1™ Gen 3<br>GM dexos 2™ | M2C917-A                                                     | RN17<br>RN0700/RN0710 | B71 2290             |               | 9.55535-S1<br>9.55535-S3                                 |                          |         | MS-11106             |                                | 18-1811 SC1    |                              |
| <b>AVIA</b> Dynetic-XT 5W-40                     | C3             | SN/CF                                    |                          | 505 00<br>505 01<br>502 00 | MB 226.5; MB 229.31<br>MB 229.51             | Longlife-04                                     | OV 0401547-D40                                                 | GM dexos 2™                                           | M2C917-A                                                     | RN0700/RN0710         |                      |               | 9.55535-GH2<br>9.55535-S2                                |                          | A40     |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-RS Premium 0W-40             | C3             | SP/SN PLUS<br>SN                         |                          | 511 00<br>G 052 579        | MB 229.31; MB 229.51<br>MB 229.52            |                                                 |                                                                | GM dexos 2™<br>GM dexos ™R                            |                                                              | RN0700/RN0710         |                      |               | 9.55535-S2                                               |                          | C40     | MS-10725<br>MS-12633 |                                |                | G 052 930-B2<br>G 052 930-2B |
| <b>AVIA</b> Dynetic-FO 5W-30                     | A5/B5          | CF; SL<br>SP/SN PLUS                     | GF-5                     | 530 36                     |                                              | Longlife-01 FE                                  |                                                                |                                                       | M2C913-A<br>M2C913-B<br>M2C913-C<br>M2C913-D                 | RN0700                |                      |               | 9.55535-G1                                               |                          |         |                      | STJLR.03.5003                  |                |                              |
| <b>AVIA</b> Dynetic-FO 0W-30                     | C2             | SN                                       | GF-5                     | 530 35                     |                                              |                                                 |                                                                |                                                       | M2C950-A                                                     |                       |                      |               | 9.55535-DS1<br>9.55535-GS1                               |                          |         |                      | STJLR.03.5007                  |                |                              |
| <b>AVIA</b> Dynetic-FO FE 0W-20                  | C5<br>C6       | SP/SN PLUS                               | GF-6 A                   |                            | MB 229.71                                    |                                                 | OV 0401547-A20                                                 | GM dexos D™                                           | M2C952-A1                                                    |                       |                      |               |                                                          |                          |         |                      | STJLR.03.5006                  |                |                              |
| <b>AVIA</b> Dynetic-FO Eco 5W-20                 | C5             | CF; SN<br>SN/RC                          | GF-5                     |                            |                                              |                                                 |                                                                |                                                       | M2C925-A<br>M2C925-B<br>M2C948-A<br>M2C948-B*                |                       |                      |               |                                                          |                          |         | MS-6395              | STJLR.03.5004                  |                |                              |
| <b>AVIA</b> Dynetic-CP 5W-30                     | C2<br>C3       | SP                                       |                          |                            | MB 226.52; MB 229.52<br>MB 229.51; MB 229.31 |                                                 |                                                                | GM dexos 2™                                           |                                                              | RN17<br>RN0700/RN0710 | B71 2290             |               | 9.55535-S1                                               |                          |         |                      |                                | 18-1811 SC1    |                              |
| <b>AVIA</b> Dynetic-CP 0W-30                     | C2             |                                          |                          |                            |                                              |                                                 |                                                                |                                                       |                                                              |                       | B71 2312             |               | 9.55535-DS1<br>9.55535-GS1                               |                          |         | MS-13340<br>MS-90047 |                                | 18-1811 SC1 LV |                              |
| <b>AVIA</b> Dynetic-CP FE 0W-20                  | C5             | SP<br>SN PLUS                            | GF-5<br>GF-6 A           |                            | MB 229.71                                    |                                                 | OV 0401547-A20                                                 |                                                       |                                                              |                       | B71 2010             |               | 9.55535-CR1<br>9.55535-DM1<br>9.55535-DSX<br>9.55535-GSX |                          |         | MS-6395              |                                |                |                              |
| <b>AVIA</b> Dynetic-FP 5W-30                     | C2<br>C3       | SP                                       |                          |                            | MB 229.31; MB 229.51                         |                                                 |                                                                |                                                       |                                                              | RN17                  | B71 2290<br>B71 2297 | FPW9.55535/03 |                                                          |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-ST 5W-30                     | C3             | SP; SQ<br>SN PLUS                        |                          |                            | MB 229.31; MB 229.51<br>MB 229.52            |                                                 | OV 0401547-D30<br>OV 0401547-G30                               | GM dexos 2™                                           |                                                              |                       | B71 2290<br>B71 2297 | FPW9.55535/03 |                                                          |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-GM D1 5W-30                  |                | SP; SP/RC<br>SN; SN PLUS<br>SN/RC        | GF-5<br>GF-6 A           | 530 34                     |                                              |                                                 |                                                                | GM dexos 1™ Gen 3<br>GM 4718M<br>GM 6094M             | M2C945-A<br>M2C946-A<br>M2C946-B1<br>M2C947-A<br>M2C961-A    |                       |                      |               | 9.55535-CR1                                              |                          |         | MS-6395<br>MS-13340  |                                |                |                              |
| <b>AVIA</b> Dynetic-RN 5W-30                     | C4             |                                          |                          |                            | MB 226.51; MB 229.31<br>MB 229.51            |                                                 |                                                                |                                                       |                                                              | RN0720                |                      |               | 9.55535-S4                                               |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-RN FE 0W-20                  | C5             | SN                                       |                          |                            |                                              |                                                 |                                                                |                                                       |                                                              | RN17 FE               |                      |               |                                                          |                          |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-VC5 0W-30                    | A5/B5<br>A7/B7 | SN/CF                                    |                          | 503 00<br>506 00<br>506 01 |                                              | Longlife-01 FE                                  |                                                                |                                                       |                                                              | RN0700                |                      |               |                                                          | VCC 95200377             |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-VC 0W-20                     | C5             | SN                                       |                          |                            |                                              |                                                 |                                                                |                                                       |                                                              |                       |                      |               | 9.55535-DM1<br>9.55535-DSX                               | VCC RBS0-2AE             |         |                      |                                |                |                              |
| <b>AVIA</b> Dynetic-HS 5W-40                     | A3/B4          | SP<br>SN/CF<br>SN PLUS                   |                          | 502 00<br>505 00           | MB 226.5; MB 229.3<br>MB 229.5               | Longlife-01                                     | GM-LL-B-025                                                    |                                                       |                                                              | RN0700/RN0710         | B71 2296             |               | 9.55535-H2/<br>M2/N2/Z2                                  |                          | A40     | MS-12991             |                                |                |                              |
| <b>AVIA</b> Dynetic-HX 10W-40                    | A3/B4          | SN/CF                                    |                          | 501 01<br>505 00           | MB 229.1H                                    |                                                 |                                                                |                                                       |                                                              | RN0700/RN0710         |                      |               | 9.55535-D2<br>9.55535-G2                                 |                          |         |                      |                                |                |                              |

