




08/2025

AVIA *Dynetic* – Motorenöle



AVIA AG
Grillparzerstr. 8 | 81675 München
info@avia.de | www.avia.de



www.avia.de



	ACEA	API	ILSAC	Volkswagen	Mercedes	BMW	Opel	GM	Ford	Renault	PSA	Stellantis	Fiat	Volvo	Porsche	Chrysler	Jaguar / Land Rover	Iveco	Bentley
AVIA <i>Dynetic racing 10W-60</i>	A3/B4	SN/CF		501 01 505 00	MB 229.3	Longlife-01													
AVIA <i>Dynetic-LL Premium 5W-30</i>	C3	SQ SP/SN PLUS		504 00 507 00 503 01	MB 229.31; MB 229.51 MB 229.52	Longlife-04	OV 0401547-D30 OV 0401547-G30 GM-LL-A-025; GM-LL-B-025	GM dexos 1™ Gen 2 GM dexos 2™					9.55535-S3		C30				
AVIA <i>Dynetic-LL VS 0W-30</i>	C3	SN		504 00 507 00	MB 229.31; MB 229.51 MB 229.52	Longlife-04							9.55535 GS1; 9.55535-DS1 9.55535-S3		C30				
AVIA <i>Dynetic-LL FE 0W-20</i>	C5 C6	SP SP/RC SN PLUS	GF-6 A	508 00 509 00					M2C956-A1						C20				
AVIA <i>Dynetic-LL IV 0W-20</i>	C5			508 00 509 00					M2C956-A1						C20				
AVIA <i>Dynetic-BM Extrem 0W-30</i>	C2 C3	SP			MB 226.5; MB 229.31 MB 229.51	Longlife-19 FE	OV 0401547-D30-G30			RN0700/RN0710			9.55535-DS1; 9.55535-GS1						
AVIA <i>Dynetic-BM Premium 0W-30</i>	C2	SP/RC SP/SN PLUS	GF-5 GF-6 A	530 35	MB 227.61; MB 229.61 DTFR 15D100	Longlife-12 FE	OV 0401547-G30		M2C950-A				9.55535-DS1; 9.55535-GS1				STJLR.03.5007		
AVIA <i>Dynetic-BM Superior 0W-20</i>	C5 C6	SQ; SQ/RC SP; SP/RC SN PLUS; SN/RC	GF-5 GF-6 A GF-7 A		MB 229.71 MB 229.72	Longlife-14 FE+ Longlife-17FE+	OV 0401547-A20	GM dexos D™	M2C947-A; M2C947-B1 M2C952-A1; M2C962-A1				9.55535-CR1; 9.55535-DM1 9.55535-DSX; 9.55535-GSX	VCC RBS0-2AE		MS-12145 MS-6395	STJLR.03.5006 STJLR.51.5122		
AVIA <i>Dynetic-SP Premium 5W-30</i>	C2 C3	SP SN PLUS		505 00 505 01 502 00	MB 226.52; MB 229.31 MB 229.51; MB 229.52	Longlife-04	OV 0401547-D30 OV 0401547-G30 GM-LL-A-025/B-025	GM dexos 1™ Gen 2 GM dexos 2™	M2C917-A	RN17 RN0700/RN0710			9.55535-S1 9.55535-S3			MS-11106		18-1811 SC1	
AVIA <i>Dynetic-XT 5W-40</i>	C3	SN/CF		505 00 505 01 502 00	MB 226.5; MB 229.31 MB 229.51	Longlife-04		GM dexos 2™	M2C917-A	RN0700/RN0710			9.55535-GH2 9.55535-S2		A40				
AVIA <i>Dynetic-RS Premium 0W-40</i>	C3	SP/SN PLUS SN		511 00 G 052 579	MB 229.31; MB 229.51 MB 229.52			GM dexos 2™ GM dexos ™R		RN0700/RN0710			9.55535-S2			MS-10725 MS-12633	C40		G 052 930-B2 G 052 930-2B
AVIA <i>Dynetic-FO 5W-30</i>	A5/B5	SP/SN PLUS	GF-5	530 36					M2C913-A; M2C913-B M2C913-C; M2C913-D	RN0700			9.55535-G1				STJLR.03.5003		
AVIA <i>Dynetic-FO 0W-30</i>	C2	SN	GF-5	530 35					M2C950-A				9.55535-DS1 9.55535-GS1				STJLR.03.5007		
AVIA <i>Dynetic-FO Eco 5W-20</i>	C5	SN	GF-5						M2C925-A; M2C948-A M2C948-B							MS-6395	STJLR.03.5004		
AVIA <i>Dynetic-FO FE 0W-20</i>	C6	SP/SN PLUS	GF-6 A		MB 229.71		OV 0401547-A20	GM dexos D™	M2C952-A1								STJLR.03.5006		
AVIA <i>Dynetic-CP 5W-30</i>	C2 C3	SP			MB 226.52; MB 229.52 MB 229.51; MB 229.31			GM dexos 2™		RN17 RN0700/RN0710	B71 2290		9.55535-S1					18-1811 SC1	
AVIA <i>Dynetic-CP 0W-30</i>	C2										B71 2312		9.55535-DS1; 9.55535-GS1					18-1811 SC1 LV	
AVIA <i>Dynetic-CP FE 0W-20</i>	C5	SP SN PLUS	GF-5 GF-6 A		MB 229.71		OV 0401547-A20				B71 2010		9.55535-CR1; 9.55535-DM1 9.55535-DSX; 9.55535-GSX			MS-6395			
AVIA <i>Dynetic-FP 5W-30</i>	C2; C3	SP			MB 229.31; MB 229.51							FPW9.55535/03							
AVIA <i>Dynetic-ST 5W-30</i>	C3	SN PLUS			MB 229.31; MB 229.51 MB 229.52			GM dexos 2™			B71 2290 B71 2297	FPW9.55535/03							
AVIA <i>Dynetic-GM D1 5W-30</i>		SP; SP/RC SN; SN PLUS SN/RC	GF-5 GF-6 A	530 34				GM dexos 1™ Gen 3	M2C945-A; M2C946-A M2C946-B1; M2C947-A M2C961-A				9.55535-CR1			MS-6395 MS-13340			
AVIA <i>Dynetic-RN 5W-30</i>	C4				MB 226.51; MB 229.31 MB 229.51					RN0720			9.55535-S4						
AVIA <i>Dynetic-RN FE 0W-20</i>	C5									RN17 FE									
AVIA <i>Dynetic-VC5 0W-30</i>	A5/B5 A7/B7	SN/CF		503 00 506 00 506 01		Longlife-01 FE				RN0700				VCC 95200377					
AVIA <i>Dynetic-VC 0W-20</i>	C5	SN											9.55535-DM1; 9.55535-DSX	VCC RBS0-2AE					
AVIA <i>Dynetic-HS 5W-40</i>	A3/B4	SN/CF		502 00 505 00	MB 226.5; MB 229.3 MB 229.5"	Longlife-01	GM-LL-B-025			RN0700/RN0710	B71 2296		9.55535-H2/M2/N2/Z2		A40	MS-12991			
AVIA <i>Dynetic-HX 10W-40</i>	A3/B4	SN/CF		501 01 505 00	MB 229.1H					RN0700/RN0710			9.55535-D2 9.55535-G2						